Reserve Study Update Pine Ridge Plantation CDD Middleburg, Florida



Prepared for FY 2024 Report Date: March 23, 2024





March 23, 2024

Ms. Marilee Giles, District Manager GMS 475 West Town Place, Suite 114 St. Augustine, Florida 32092

Re: Pine Ridge Plantation CDD

Dear Ms. Giles:

Community Advisors is pleased to provide this Revised Reserve Study report for the above referenced Association. We have completed the adjustments you requested and have updated your funding plan. We recommend updating your study every 2 years to keep your information current with changing replacement cost, interest and inflation rates.

It has been a pleasure serving you and please let me know if you have any questions or concerns.

Respectively submitted,

CRShapparl

Charles R. Sheppard *RS PRA CCI* Professional Reserve Analyst 10459 Hunters Creek Court Jacksonville, Fl. 32256





construction inspectors

SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH QUALIFIED CONSULTANTS.

TABLE OF CONTENTS

EXECUTIVE SUMMARY

Executive Summary	
Financial Summary - Recommended Funding Plan	
Cash Flow Funding Plan VS Fully Funded	
Current Funding Plan vs Recommended Funding Plan	
CURRENT FUNDING PLAN	
Financial Summary - Current Funding Plan	
Current Funding Plan Projection	
CASH FLOW	
Income & Expense Spreadsheet	
EXPENDITURE DETAIL	
Annual Expenditure Detail	
Asset Current Cost by Category	
COMPONENT INVENTORY	
Component Inventory	
Component Detail Index	
Component Detail	
DISCLOSURERS & INFORMATION	
Report Navigation	
Methodology & Information	
Terms of Service	

Executive Summary

Account Information

Account Name City State In Service Date Total Units Study Level	Pine Ridge Plantation CDD Middleburg Florida June, 15 2008 737 Level II Update	Account Number Last Site Visit Report Date Report Version Fiscal Year Start Fiscal year End	2022 March, 4 2024 March, 23 2024 2 October, 1 2024 September, 30 2025
Reserve Fund I	nformation		
Current Component Re Number of Component Reserve Fund Beginni Billing Term	is	\$1,667,265 93 \$717,350 Annually	
Component Fu	nding (Straight Line)		
Recommended First Y Interest Rate on Reser Inflation Rate on Repla	•	\$70,457 0% 0%	
Pooled Cash (C	urrent Funding Plan)		
Current Year Reserve Interest Rate on Reser Inflation Rate on Repla Annual Contribution Inc	ve Deposits acement Cost	\$82,202 3.0% 3.5% 3.0%	
Pooled Cash (R	ecommended Funding P	lan)	
Recommended First Y Interest Rate on Reser Inflation Rate on Repla Annual Contribution In	acement Cost	\$83,529 3.0% 3.5% 3.0%	

Comment

- Current funding plan maintains adequate funding.
- Recommended funding plan maintains adequate funding with larger year end balances.
- This analysis should be updated annualy with a site visit every 2 years to monitor component condition and update component replacement cost, interest and inflation rates.

Pine Ridge Plantation CDD Financial Summary - Recommended Funding Plan

	-	-	nce: \$717,350		ly Funde	d: \$710,533		ate:0%		
	- The second sec			. OT				ę		e e
	Contra	i Or	17 2° 20	\$, ~~	چ ر	چ ج		. 200 20	250 25	in the se
Year	A Contraction of the second se	The Part of the Pa	And Control	OBO TROM	the second	A. A. C. A.	Arost Contraction	Leon Digition	لي الألي التي التي التي التي التي التي التي ال	est france
24-25	1,667,265	3.5%	83,529	0	3.00%	23,355	22,380	801,854	798,751	100%
25-26	1,721,707	3.5%	86,035	0	3.00%	26,171	15,525	898,535	899,238	100%
26-27	1,781,967	3.5%	88,616	0	3.00%	25,545	135,660	877,036	882,527	99%
27-28	1,844,336	3.5%	91,275	0	3.00%	27,027	67,410	927,928	939,165	99%
28-29	1,908,887	3.5%	94,013	0	3.00%	30,348	10,328	1,041,961	1,060,209	98%
29-30	1,975,698	3.5%	96,833	0	3.00%	33,102	35,393	1,136,504	1,163,123	98%
30-31	2,044,848	3.5%	99,738	0	3.00%	35,723	45,473	1,226,492	1,262,792	97%
31-32	2,116,417	3.5%	102,730	0	3.00%	39,228	21,629	1,346,822	1,394,339	97%
32-33	2,190,492	3.5%	105,812	0	3.00%	34,738	294,711	1,192,661	1,251,690	95%
33-34	2,209,918	3.5%	108,987	0	3.00%	36,146	96,766	1,241,028	1,308,157	95%
34-35	2,223,788	3.5%	112,256	0	3.00%	31,167	314,383	1,070,069	1,143,310	94%
35-36	2,301,620	3.5%	115,624	0	3.00%	35,177	13,140	1,207,730	1,291,110	94%
36-37	2,382,177	3.5%	119,093	0	3.00%	37,894	63,676	1,301,040	1,396,027	93%
37-38	2,461,956	3.5%	122,665	0	3.00%	33,891	293,992	1,163,605	1,270,104	92%
38-39	2,548,125	3.5%	126,345	0	3.00%	31,189	250,302	1,070,838	1,189,802	90%
39-40	2,637,309	3.5%	130,136	0	3.00%	35,253	25,867	1,210,359	1,343,706	90%
40-41	2,729,615	3.5%	134,040	0	3.00%	39,552	26,010	1,357,941	1,507,717	90%
41-42	2,825,151	3.5%	138,061	0	3.00%	44,318	18,736	1,521,584	1,690,032	90%
42-43	2,924,032	3.5%	142,203	0	3.00%	45,000	163,793	1,544,993	1,733,807	89%
43-44	3,026,373	3.5%	146,469	0	3.00%	48,783	65,365	1,674,880	1,886,383	89%
44-45	3,132,296	3.5%	150,863	0	3.00%	53,898	29,134	1,850,507	2,087,381	89%
45-46	3,241,926	3.5%	155,389	0	3.00%	59,621	18,535	2,046,982	2,312,165	89%
46-47	3,355,393	3.5%	160,051	0	3.00%	58,960	241,696	2,024,296	2,319,826	87%
47-48	3,472,832	3.5%	164,852	0	3.00%	41,401	809,128	1,421,421	1,740,273	82%
48-49	3,594,381	3.5%	169,798	0	3.00%	45,435	76,720	1,559,934	1,911,753	82%
49-50	3,684,736	3.5%	174,892	0	3.00%	49,932	70,425	1,714,333	2,099,576	82%
50-51	3,813,702	3.5%	180,138	0	3.00%	47,541	309,756	1,632,257	2,054,509	79%
51-52	3,947,181	3.5%	185,543	0	3.00%	52,237	76,555	1,793,482	2,256,300	79%
52-53	4,085,333	3.5%	191,109	0	3.00%	34,209	844,293	1,174,507	1,677,864	70%
53-54	4,228,319	3.5%	196,842	0	3.00%	39,025	70,509	1,339,866	1,887,624	71%





Chart illustrates year end balances and expenditures with the level of contributions necessary to maintain adequate funding.

Community Advisors Page 1-3 March 23, 2024




This chart illustrates annual expenditures and compares the current funding plan to the recommended funding plan.

Community Advisors Page 1-4 March 23, 2024

Pine Ridge Plantation CDD Financial Summary - Current Funding Plan

	-	-	ce: \$717,350		ly Fundeo	d: \$710,533	Tax R	ate:0%		
	ent le		i.	Şr.				e X		
	Nº ST	ion	Jan Line Line			C.		ALL ALL	AND AND	KIN NO
Year	A Constant	Will 200	Finds Continue	Other theolde	P. C.	A. A. C. A.	ALO CO	A CONTRACT OF CONTRACT.	ن نابان کو ^{ی ای} ک کو ^{ی ای} ک	CC
24-25	1,667,265	3.5%	82,202	0	3.00%	23,315	22,380	800,487	798,751	100%
25-26	1,721,707	3.5%	84,668	0	3.00%	26,089	15,525	895,719	899,238	100%
26-27	1,781,967	3.5%	87,208	0	3.00%	25,418	135,660	872,685	882,527	99%
27-28	1,844,336	3.5%	89,824	0	3.00%	26,853	67,410	921,953	939,165	98%
28-29	1,908,887	3.5%	92,519	0	3.00%	30,124	10,328	1,034,268	1,060,209	98%
29-30	1,975,698	3.5%	95,295	0	3.00%	32,825	35,393	1,126,995	1,163,123	97%
30-31	2,044,848	3.5%	98,153	0	3.00%	35,390	45,473	1,215,066	1,262,792	96%
31-32	2,116,417	3.5%	101,098	0	3.00%	38,836	21,629	1,333,372	1,394,339	96%
32-33	2,190,492	3.5%	104,131	0	3.00%	34,284	294,711	1,177,075	1,251,690	94%
33-34	2,209,918	3.5%	107,255	0	3.00%	35,627	96,766	1,223,191	1,308,157	94%
34-35	2,223,788	3.5%	110,473	0	3.00%	30,578	314,383	1,049,860	1,143,310	92%
35-36	2,301,620	3.5%	113,787	0	3.00%	34,515	13,140	1,185,022	1,291,110	92%
36-37	2,382,177	3.5%	117,200	0	3.00%	37,156	63,676	1,275,702	1,396,027	91%
37-38	2,461,956	3.5%	120,716	0	3.00%	33,073	293,992	1,135,499	1,270,104	89%
38-39	2,548,125	3.5%	124,338	0	3.00%	30,286	250,302	1,039,821	1,189,802	87%
39-40	2,637,309	3.5%	128,068	0	3.00%	34,261	25,867	1,176,282	1,343,706	88%
40-41	2,729,615	3.5%	131,910	0	3.00%	38,465	26,010	1,320,648	1,507,717	88%
41-42	2,825,151	3.5%	135,867	0	3.00%	43,133	18,736	1,480,912	1,690,032	88%
42-43	2,924,032	3.5%	139,943	0	3.00%	43,712	163,793	1,500,774	1,733,807	87%
43-44	3,026,373	3.5%	144,142	0	3.00%	47,387	65,365	1,626,937	1,886,383	86%
44-45	3,132,296	3.5%	148,466	0	3.00%	52,388	29,134	1,798,657	2,087,381	86%
45-46	3,241,926	3.5%	152,920	0	3.00%	57,991	18,535	1,991,033	2,312,165	86%
46-47	3,355,393	3.5%	157,508	0	3.00%	57,205	241,696	1,964,050	2,319,826	85%
47-48	3,472,832	3.5%	162,233	0	3.00%	39,515	809,128	1,356,669	1,740,273	78%
48-49	3,594,381	3.5%	167,100	0	3.00%	43,411	76,720	1,490,461	1,911,753	78%
49-50	3,684,736	3.5%	172,113	0	3.00%	47,764	70,425	1,639,913	2,099,576	78%
50-51	3,813,702	3.5%	177,276	0	3.00%	45,223	309,756	1,552,656	2,054,509	76%
51-52	3,947,181	3.5%	182,594	0	3.00%	49,761	76,555	1,708,457	2,256,300	76%
52-53	4,085,333	3.5%	188,072	0	3.00%	31,567	844,293	1,083,803	1,677,864	65%
53-54	4,228,319	3.5%	193,714	0	3.00%	36,210	70,509	1,243,219	1,887,624	66%



This chart illustrates how the CDD's current funding plan will perform over time.

Community Advisors Page 2-2 March 23, 2024

	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34
Beginning Balance Annual Assessment Interest Earned	717,350 83,529 23,355	801,854 86,035 26,171	898,535 88,616 25,545	877,036 91,275 27,027	927,928 94,013 30,348	1,041,961 96,833 33,102	1,136,504 99,738 35,723	1,226,492 102,730 39,228	1,346,822 105,812 34,738	1,192,661 108,987 36,146
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	22,380 798,751 100% 801,854	15,525 899,238 100% 898,535	135,660 882,527 99% 877,036	67,410 939,165 99% 927,928	10,328 1,060,209 98% 1,041,961	35,393 1,163,123 98% 1,136,504	45,473 1,262,792 97% 1,226,492	21,629 1,394,339 97% 1,346,822	294,711 1,251,690 95% 1,192,661	96,766 1,308,157 95% 1,241,028
Description Misc. Site Components										
Monument Sign (Large) Refurbishment Monument Sign (Small) Refurbishment		4,140 2,070								
Misc. Site Components Total:		6,210								
Fence & Gates Aluminum Fencing - Pool Aluminum Gates/Fence- Entry										
Chain Link Fence VC - Sport Courts Chain Link Fence/Gates - Dumpster Viny Ranch Fence - Tynes Blvd.									3,034	
Vinyl Fencing - Pine Ridge Pkwy Fence & Gates Total:									3,455 6,489	
Parking Lots									0,407	
Asphalt Resurfacing - Phase I Asphalt Resurfacing - Phase II									66,367	
Concrete Curbing Allow at Paving - Phase I Concrete Curbing Allow at Paving - Phase II									5,004	
Parking Lots Total:									71,371	
Site Lighting Decorative Light Poles - Parking Lot									22,122	
Decorative Light Poles - Playgound/Trail									36,871	
Decorative Light Poles - Pool Light Fixtures - Concrete Poles									41,084	
Site Lighting Total:									100,077	

	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34
Description										
Misc. Building Components										
Exterior Door/Window Allowance (Partial Replace)										
Folding Partition - Meeting Room Refurbish Allowance - Clubhouse Restrooms										
Refurbish Allowance - Clubhouse Restrooms Refurbish Allowance - Locker Rooms										
Misc. Building Components Total:										
Roofing										
Metal Roof - Clubhouse										
Metal Roof - Pool Slide Tower										
Roofing Total:										
Cabinets & Tops										
Cabinets & Top - Outdoor Gathering				3,659						
Cabinets & Tops - Meeting Area Cabinets & Tops - Serving Room									5,899 12,220	
Cabinets & Tops - Serving Room				3,659					12,220	
-				0,000					10,115	
Exterior Painting										22 160
Painting - Clubhouse Siding & Trim Painting - Pool Slide Stairs							4,671			23,169
Exterior Painting Total:							4,671			23,169
Flooring										
Carpet - Clubhouse (replace with vinyl)	3,780									
Rubber Floor - Fitness Room	- ,								5,804	
Tile Floor - Serving Room									4,365	
Vinyl Plank Floor - Activity Room/Corridor									7,577	
Wood Floor - Family Gathering Room	3,780								17,747	
-	5,700								1/,/4/	
Furniture Fixtures & Equipment				2 001						
Access Control System Ceiling Fans - Exterior				3,881						
Ceiling Fans - Family Gathering Room										

	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34
Description										
Furniture Fixtures & Equipment continued										
Ceiling Fans - Fitness Center										
Fitness Equip. Allowance (partial replacement)	3,000	3,105	3,214	3,326	3,443	3,563	3,688	3,817	3,950	4,089
Fitness Equip. Replace Allowance										
Furniture Allowance - Clubhouse						14,252				
Office Furniture	3,000	3,105	2 214	2 226	2 1 1 2	2,375 3,563	3,688	3,817	3,950	4,089
Pool/Patio Furniture Allowance (partial replaceme Pool/Patio Furniture Replacement Allowance	5,000	5,105	3,214	3,326	3,443	5,505	5,088	5,817	55,306	4,089
Security Camera System Allowance									55,500	
Furniture Fixtures & Equipment Total:	6,000	6,210	6,427	10,533	6,885	23,754	7,376	7,634	63,207	8,177
HVAC Equipment										
Air Handler (refurbished)										
HVAC Unit 1										
HVAC Unit 2								10,178		
HVAC Unit 3 A Condensor	6,000									
HVAC Unit 3 B Condensor	3,600							40.480		
HVAC Equipment Total:	9,600							10,178		
Life Safety Systems										
Fire Alarm Panel						8,076				
Life Safety Systems Total:						8,076				
Playground										
Playground Equipment Allowance				27,718						
Wood Benches/Tables				27,710					6,321	
Playground Total:				27,718					6,321	
Sport Courts										
Drinking Fountain										
Shade Fabric - Sport Courts										
Shade Structure Replacement - Sport Courts										
Sport Court Replacement										
Sport Court Resurfacing (color coat)							29,738			
Sport Courts Total:							29,738			

	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34
Description										
Swimming Pool										
Concrete Pavers - Pool Deck/Patio										
Fiberglass Refurbish Allow - Pool Slide										
Filtration Equip Allowance (partial replacement)	3,000	3,105	3,214	3,326	3,443	3,563	3,688	3,817	3,950	4,089
Filtration System Refurishment Allowance										
Pool Lift									7,429	
Pool Resurfacing/Tile			126,019							
Pool Splash Equipment Allowance				22,174						
Refurbish Allowance - Pool Slide Frame										
Shade Fabric - Pool										
Shade Structure Replacement										61,330
Splash Pad Equipment Allowance										
Swimming Pool Total:	3,000	3,105	129,233	25,501	3,443	3,563	3,688	3,817	11,380	65,419
Operating Expense										
Backflow Preventer Repair	Unfunded									
Electrical Panels/Disconnects	Unfunded									
Fire Detection Devices	Unfunded									
Flag Pole	Unfunded									
Grills	Unfunded									
Interior Painting - Clubhouse	Unfunded									
Laminated Beam Repair	Unfunded									
Message Board	Unfunded									
Painting - Entry Features	Unfunded									
Painting - Pool Equipment Yard	Unfunded									
Pendent Lights - Breezeway	Unfunded									
Refrigerator	Unfunded									
Splash Pad Coating/Repair	Unfunded									
Sport Court Nets/Equipment	Unfunded									
Trash Cans/ Misc. Site Furnishings	Unfunded									
Water Coolers - Clubhouse	Unfunded									
Water Heater - Clubhouse	Unfunded									

	24-25	25-26	26-27	27-28	28-29	29-30	30-31	31-32	32-33	33-34
Description										
Components Not Included										
Backflow Preventer Replacement	Unfunded									
Building Foundation/Frame	Unfunded									
Communication Wiring/Devices in Building	Unfunded									
Electrical Wiring/Devices in Building	Unfunded									
Light Poles (Concrete) - Parking Lot	Unfunded									
Siding/Trim Replacement	Unfunded									
Site Utilities	Unfunded									
Water/Sewer/Vent Piping In building	Unfunded									
Components Removed										
Wood Pergolas - Entry Signs	Unfunded									
- Year Total:	22,380	15,525	135,660	67,410	10,328	35,393	45,473	21,629	294,711	96,766

	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44
Beginning Balance Annual Assessment Interest Earned	1,241,028 112,256 31,167	1,070,069 115,624 35,177	1,207,730 119,093 37,894	1,301,040 122,665 33,891	1,163,605 126,345 31,189	1,070,838 130,136 35,253	1,210,359 134,040 39,552	1,357,941 138,061 44,318	1,521,584 142,203 45,000	1,544,993 146,469 48,783
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	314,383 1,143,310 94% 1,070,069	13,140 1,291,110 94% 1,207,730	63,676 1,396,027 93% 1,301,040	293,992 1,270,104 92% 1,163,605	250,302 1,189,802 90% 1,070,838	25,867 1,343,706 90% 1,210,359	26,010 1,507,717 90% 1,357,941	18,736 1,690,032 90% 1,521,584	163,793 1,733,807 89% 1,544,993	65,365 1,886,383 89% 1,674,880
Description Misc. Site Components Monument Sign (Large) Refurbishment							6,936			
Monument Sign (Small) Refurbishment Misc. Site Components Total:							3,468 10,404			
Fence & Gates Aluminum Fencing - Pool										
Aluminum Gates/Fence- Entry Chain Link Fence VC - Sport Courts Chain Link Fence/Gates - Dumpster									7,801	
Viny Ranch Fence - Tynes Blvd. Vinyl Fencing - Pine Ridge Pkwy Fence & Gates Total:									7,801	
Parking Lots Asphalt Resurfacing - Phase I										
Asphalt Resurfacing - Phase II Concrete Curbing Allow at Paving - Phase I										
Concrete Curbing Allow at Paving - Phase II Parking Lots Total:										
Site Lighting Decorative Light Poles - Parking Lot Decorative Light Poles - Playgound/Trail										
Decorative Light Poles - Pool Light Fixtures - Concrete Poles Site Lighting Total:									11,888 11,888	

	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44
Description										
Misc. Building Components										
Exterior Door/Window Allowance (Partial Replace)										
Folding Partition - Meeting Room				4,473						
Refurbish Allowance - Clubhouse Restrooms	46,945									
Refurbish Allowance - Locker Rooms	146,973 193,918			4,473						
Mise. Building Components Total.	195,918			4,475						
Roofing										
Metal Roof - Clubhouse				270,940						
Metal Roof - Pool Slide Tower				4,504						
Roofing Total:				275,444						
Cabinets & Tops										
Cabinets & Top - Outdoor Gathering										
Cabinets & Tops - Meeting Area										
Cabinets & Tops - Serving Room										
Cabinets & Tops Total:										
Exterior Painting										
Painting - Clubhouse Siding & Trim										32,683
Painting - Pool Slide Stairs					6,151					
Exterior Painting Total:					6,151					32,683
Flooring										
Carpet - Clubhouse (replace with vinyl)										
Rubber Floor - Fitness Room										
Tile Floor - Serving Room										
Vinyl Plank Floor - Activity Room/Corridor										
Wood Floor - Family Gathering Room									18,723	
Flooring Total:									18,723	
Furniture Fixtures & Equipment										
Access Control System									6,501	
Ceiling Fans - Exterior			9,429							
Ceiling Fans - Family Gathering Room								2,584		

	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44
Description										
Furniture Fixtures & Equipment continued										
Ceiling Fans - Fitness Center						2,413				
Fitness Equip. Allowance (partial replacement)	4,232	4,380	4,533	4,692	4,856	5,026	5,202	5,384	5,572	5,768
Fitness Equip. Replace Allowance										
Furniture Allowance - Clubhouse										
Office Furniture	4,232	4,380	4,533	4 (0)	4,856	5.026	5,202	5,384	5,572	5769
Pool/Patio Furniture Allowance (partial replaceme Pool/Patio Furniture Replacement Allowance	4,232	4,380	4,335	4,692	4,830	5,026	5,202	3,384	5,572	5,768
Security Camera System Allowance			22,666							
Furniture Fixtures & Equipment Total:	8,464	8,760	41,162	9,384	9,712	12,465	10,404	13,352	17,646	11,535
	,	,	,	,	,	,	,	,	,	,
HVAC Equipment						0 277				
Air Handler (refurbished) HVAC Unit 1	11,849					8,377				
HVAC Unit 2	11,049									15,380
HVAC Unit 2 A Condensor			9,066							15,500
HVAC Unit 3 B Condensor			5,440							
HVAC Equipment Total:	11,849		14,506			8,377				15,380
Life Safety Systems										
Fire Alarm Panel										
Life Safety Systems Total:										
Playground										
Playground Equipment Allowance									46,437	
Wood Benches/Tables									,	
Playground Total:									46,437	
Sport Courts										
Drinking Fountain										
Shade Fabric - Sport Courts			3,475							
Shade Structure Replacement - Sport Courts										
Sport Court Replacement					20.150					
Sport Court Resurfacing (color coat)			0.455		39,159					
Sport Courts Total:			3,475		39,159					

Community Advisors Page 3-8 March 23, 2024

	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44
Description										
Swimming Pool										
Concrete Pavers - Pool Deck/Patio										
Fiberglass Refurbish Allow - Pool Slide	40,907									
Filtration Equip Allowance (partial replacement)	4,232	4,380	4,533	4,692	4,856	5,026	5,202	5,384	5,572	5,768
Filtration System Refurishment Allowance									55,725	
Pool Lift										
Pool Resurfacing/Tile					190,423					
Pool Splash Equipment Allowance										
Refurbish Allowance - Pool Slide Frame	55,013									
Shade Fabric - Pool										
Shade Structure Replacement										
Splash Pad Equipment Allowance										
Swimming Pool Total:	100,153	4,380	4,533	4,692	195,279	5,026	5,202	5,384	61,297	5,768
Operating Expense										
Backflow Preventer Repair	Unfunded									
Electrical Panels/Disconnects	Unfunded									
Fire Detection Devices	Unfunded									
Flag Pole	Unfunded									
Grills	Unfunded									
Interior Painting - Clubhouse	Unfunded									
Laminated Beam Repair	Unfunded									
Message Board	Unfunded									
Painting - Entry Features	Unfunded									
Painting - Pool Equipment Yard	Unfunded									
Pendent Lights - Breezeway	Unfunded									
Refrigerator	Unfunded									
Splash Pad Coating/Repair	Unfunded									
Sport Court Nets/Equipment	Unfunded									
Trash Cans/ Misc. Site Furnishings	Unfunded									
Water Coolers - Clubhouse	Unfunded									
Water Heater - Clubhouse	Unfunded									

	34-35	35-36	36-37	37-38	38-39	39-40	40-41	41-42	42-43	43-44
Description										
Components Not Included										
Backflow Preventer Replacement	Unfunded									
Building Foundation/Frame	Unfunded									
Communication Wiring/Devices in Building	Unfunded									
Electrical Wiring/Devices in Building	Unfunded									
Light Poles (Concrete) - Parking Lot	Unfunded									
Siding/Trim Replacement	Unfunded									
Site Utilities	Unfunded									
Water/Sewer/Vent Piping In building	Unfunded									
Components Removed										
Wood Pergolas - Entry Signs	Unfunded									
= Year Total:	314,383	13,140	63,676	293,992	250,302	25,867	26,010	18,736	163,793	65,365

	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54
Beginning Balance Annual Assessment Interest Earned	1,674,880 150,863 53,898	1,850,507 155,389 59,621	2,046,982 160,051 58,960	2,024,296 164,852 41,401	1,421,421 169,798 45,435	1,559,934 174,892 49,932	1,714,333 180,138 47,541	1,632,257 185,543 52,237	1,793,482 191,109 34,209	1,174,507 196,842 39,025
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	29,134 2,087,381 89% 1,850,507	18,535 2,312,165 89% 2,046,982	241,696 2,319,826 87% 2,024,296	809,128 1,740,273 82% 1,421,421	76,720 1,911,753 82% 1,559,934	70,425 2,099,576 82% 1,714,333	309,756 2,054,509 79% 1,632,257	76,555 2,256,300 79% 1,793,482	844,293 1,677,864 70% 1,174,507	70,509 1,887,624 71% 1,339,866
Description Misc. Site Components Monument Sign (Large) Refurbishment										
Monument Sign (Small) Refurbishment Misc. Site Components Total:										
Fence & Gates Aluminum Fencing - Pool Aluminum Gates/Fence- Entry				164,956						
Chain Link Fence VC - Sport Courts Chain Link Fence/Gates - Dumpster				28,168					185,634	
Viny Ranch Fence - Tynes Blvd. Vinyl Fencing - Pine Ridge Pkwy Fence & Gates Total:				193,123					185,634	
Parking Lots Asphalt Resurfacing - Phase I										
Asphalt Resurfacing - Phase I Asphalt Resurfacing - Phase II Concrete Curbing Allow at Paving - Phase I				102,571						
Concrete Curbing Allow at Paving - Phase II Parking Lots Total:				8,383 110,954						
Site Lighting Decorative Light Poles - Parking Lot Decorative Light Poles - Playgound/Trail Decorative Light Poles - Pool										
Light Fixtures - Concrete Poles Site Lighting Total:										

	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54
Description										
Misc. Building Components										
Exterior Door/Window Allowance (Partial Replace)									104,807	
Folding Partition - Meeting Room Refurbish Allowance - Clubhouse Restrooms										
Refurbish Allowance - Clubhouse Restrooms Refurbish Allowance - Locker Rooms										
Misc. Building Components Total:									104,807	
Roofing									,	
Metal Roof - Clubhouse										
Metal Roof - Pool Slide Tower										
Roofing Total:										
Cabinets & Tops										
Cabinets & Top - Outdoor Gathering				7,280						
Cabinets & Tops - Meeting Area										
Cabinets & Tops - Serving Room										
Cabinets & Tops Total:				7,280						
Exterior Painting										
Painting - Clubhouse Siding & Trim										46,102
Painting - Pool Slide Stairs			8,100							46 102
Exterior Painting Total:			8,100							46,102
Flooring										
Carpet - Clubhouse (replace with vinyl)										
Rubber Floor - Fitness Room Tile Floor - Serving Room										
Vinyl Plank Floor - Activity Room/Corridor										
Wood Floor - Family Gathering Room										
Flooring Total:										
Furniture Fixtures & Equipment										
Access Control System										
Ceiling Fans - Exterior								15,797		
Ceiling Fans - Family Gathering Room										

	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54
Description										
Furniture Fixtures & Equipment continued										
Ceiling Fans - Fitness Center										
Fitness Equip. Allowance (partial replacement)	5,969	6,178	6,395		6,850	7,090	7,338	7,595	7,861	8,136
Fitness Equip. Replace Allowance				88,245						
Furniture Allowance - Clubhouse						28,359				
Office Furniture	5.000	c 170	C 205	C (10	C 950	4,726	7 220	7 505	7.061	9.126
Pool/Patio Furniture Allowance (partial replaceme Pool/Patio Furniture Replacement Allowance	5,969	6,178	6,395	6,618	6,850	7,090	7,338	7,595	7,861	8,136
Security Camera System Allowance								37,974		
Furniture Fixtures & Equipment Total:	11,939	12,357	12,789	94,863	13,700	47,265	14,676	68,960	15,721	16,271
HVAC Equipment										
Air Handler (refurbished)										
HVAC Unit 1			17,905							
HVAC Unit 2										
HVAC Unit 3 A Condensor					13,700					
HVAC Unit 3 B Condensor					8,220					
HVAC Equipment Total:			17,905		21,920					
Life Safety Systems										
Fire Alarm Panel						16,070				
Life Safety Systems Total:						16,070				
Playground										
Playground Equipment Allowance										
Wood Benches/Tables									12,577	
Playground Total:									12,577	
Sport Courts										
Drinking Fountain									12,577	
Shade Fabric - Sport Courts										
Shade Structure Replacement - Sport Courts					34,250					
Sport Court Replacement									505,117	
Sport Court Resurfacing (color coat)			51,566							
Sport Courts Total:			51,566		34,250				517,694	

Community Advisors Page 3-13 March 23, 2024

	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54
Description										
Swimming Pool										
Concrete Pavers - Pool Deck/Patio				244,287						
Fiberglass Refurbish Allow - Pool Slide			61,814							
Filtration Equip Allowance (partial replacement)	5,969	6,178	6,395	6,618	6,850	7,090	7,338	7,595	7,861	8,136
Filtration System Refurishment Allowance										
Pool Lift	11,226									
Pool Resurfacing/Tile							287,743			
Pool Splash Equipment Allowance				44,122						
Refurbish Allowance - Pool Slide Frame			83,129							
Shade Fabric - Pool				15,222						
Shade Structure Replacement										
Splash Pad Equipment Allowance				92,657						
Swimming Pool Total:	17,196	6,178	151,337	402,907	6,850	7,090	295,080	7,595	7,861	8,136
Operating Expense										
Backflow Preventer Repair	Unfunded									
Electrical Panels/Disconnects	Unfunded									
Fire Detection Devices	Unfunded									
Flag Pole	Unfunded									
Grills	Unfunded									
Interior Painting - Clubhouse	Unfunded									
Laminated Beam Repair	Unfunded									
Message Board	Unfunded									
Painting - Entry Features	Unfunded									
Painting - Pool Equipment Yard	Unfunded									
Pendent Lights - Breezeway	Unfunded									
Refrigerator	Unfunded									
Splash Pad Coating/Repair	Unfunded									
Sport Court Nets/Equipment	Unfunded									
Trash Cans/ Misc. Site Furnishings	Unfunded									
Water Coolers - Clubhouse	Unfunded									
Water Heater - Clubhouse	Unfunded									

	44-45	45-46	46-47	47-48	48-49	49-50	50-51	51-52	52-53	53-54
Description										
Components Not Included										
Backflow Preventer Replacement	Unfunded									
Building Foundation/Frame	Unfunded									
Communication Wiring/Devices in Building	Unfunded									
Electrical Wiring/Devices in Building	Unfunded									
Light Poles (Concrete) - Parking Lot	Unfunded									
Siding/Trim Replacement	Unfunded									
Site Utilities	Unfunded									
Water/Sewer/Vent Piping In building	Unfunded									
Components Removed										
Wood Pergolas - Entry Signs	Unfunded									
Year Total:	29,134	18,535	241,696	809,128	76,720	70,425	309,756	76,555	844,293	70,509

Description	Expenditures
Replacement Year 24-25	
Flooring	
Carpet - Clubhouse (replace with vinyl)	3,780
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,000
Pool/Patio Furniture Allowance (partial replacement)	3,000
HVAC Equipment	
HVAC Unit 3 A Condensor	6,000
HVAC Unit 3 B Condensor	3,600
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,000
Total for 2024 - 2025	\$22,380
Replacement Year 25-26	
Misc. Site Components	
Monument Sign (Large) Refurbishment	4,140
Monument Sign (Small) Refurbishment	2,070
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,105
Pool/Patio Furniture Allowance (partial replacement)	3,105
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,105
Total for 2025 - 2026	\$15,525
Replacement Year 26-27	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,214
Pool/Patio Furniture Allowance (partial replacement)	3,214
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,214
Pool Resurfacing/Tile	126,019
Total for 2026 - 2027	\$135,660
Replacement Year 27-28	
Cabinets & Tops	
Cabinets & Top - Outdoor Gathering	3,659
	- 7

Description	Expenditures
Replacement Year 27-28 continued	
Furniture Fixtures & Equipment	
Access Control System	3,881
Fitness Equip. Allowance (partial replacement)	3,326
Pool/Patio Furniture Allowance (partial replacement)	3,326
Playground	
Playground Equipment Allowance	27,718
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,326
Pool Splash Equipment Allowance	22,174
Total for 2027 - 2028	\$67,410
Replacement Year 28-29	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,443
Pool/Patio Furniture Allowance (partial replacement)	3,443
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,443
Total for 2028 - 2029	\$10,328
Replacement Year 29-30	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,563
Furniture Allowance - Clubhouse	14,252
Office Furniture	2,375
Pool/Patio Furniture Allowance (partial replacement)	3,563
Life Safety Systems	
Fire Alarm Panel	8,076
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,563
Total for 2029 - 2030	\$35,393
Replacement Year 30-31	
Exterior Painting	
Painting - Pool Slide Stairs	4,671

Description	Expenditures
Replacement Year 30-31 continued	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,688
Pool/Patio Furniture Allowance (partial replacement)	3,688
Sport Courts	
Sport Court Resurfacing (color coat)	29,738
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,688
Total for 2030 - 2031	\$45,473
Replacement Year 31-32	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,817
Pool/Patio Furniture Allowance (partial replacement)	3,817
HVAC Equipment	
HVAC Unit 2	10,178
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,817
Total for 2031 - 2032	\$21,629
Replacement Year 32-33	
Fence & Gates	
Chain Link Fence/Gates - Dumpster	3,034
Vinyl Fencing - Pine Ridge Pkwy	3,455
Parking Lots	
Asphalt Resurfacing - Phase I	66,367
Concrete Curbing Allow at Paving - Phase I	5,004
Site Lighting	
Decorative Light Poles - Parking Lot	22,122
Decorative Light Poles - Playgound/Trail	36,871
Decorative Light Poles - Pool	41,084
Cabinets & Tops	- 00-
Cabinets & Tops - Meeting Area	5,899
Cabinets & Tops - Serving Room	12,220

Description	Expenditures
Replacement Year 32-33 continued	
Flooring	
Rubber Floor - Fitness Room	5,804
Tile Floor - Serving Room	4,365
Vinyl Plank Floor - Activity Room/Corridor	7,577
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	3,950
Pool/Patio Furniture Allowance (partial replacement)	3,950
Pool/Patio Furniture Replacement Allowance	55,306
Playground	
Wood Benches/Tables	6,321
Swimming Pool	
Filtration Equip Allowance (partial replacement)	3,950
Pool Lift	7,429
Total for 2032 - 2033	\$294,711
Replacement Year 33-34	
Exterior Painting	
Painting - Clubhouse Siding & Trim	23,169
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	4,089
Pool/Patio Furniture Allowance (partial replacement)	4,089
Swimming Pool	
Filtration Equip Allowance (partial replacement)	4,089
Shade Structure Replacement	61,330
Total for 2033 - 2034	\$96,766
Replacement Year 34-35	
Misc. Building Components	
Refurbish Allowance - Clubhouse Restrooms	46,945
Refurbish Allowance - Locker Rooms	146,973
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	4,232
Pool/Patio Furniture Allowance (partial replacement)	4,232

Description	Expenditures
Replacement Year 34-35 continued	
HVAC Equipment	
HVAC Unit 1	11,849
Swimming Pool	
Fiberglass Refurbish Allow - Pool Slide	40,907
Filtration Equip Allowance (partial replacement)	4,232
Refurbish Allowance - Pool Slide Frame	55,013
Total for 2034 - 2035	\$314,383
Replacement Year 35-36	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	4,380
Pool/Patio Furniture Allowance (partial replacement)	4,380
Swimming Pool	
Filtration Equip Allowance (partial replacement)	4,380
Total for 2035 - 2036	\$13,140
Replacement Year 36-37	
Furniture Fixtures & Equipment	
Ceiling Fans - Exterior	9,429
Fitness Equip. Allowance (partial replacement)	4,533
Pool/Patio Furniture Allowance (partial replacement)	4,533
Security Camera System Allowance	22,666
HVAC Equipment	0.077
HVAC Unit 3 A Condensor HVAC Unit 3 B Condensor	9,066
	5,440
Sport Courts	2 175
Shade Fabric - Sport Courts	3,475
Swimming Pool	1 522
Filtration Equip Allowance (partial replacement)	4,533
Total for 2036 - 2037	\$63,676
Replacement Year 37-38	
Misc. Building Components	
Folding Partition - Meeting Room	4,473

Description	Expenditures
Replacement Year 37-38 continued	
Roofing	
Metal Roof - Clubhouse	270,940
Metal Roof - Pool Slide Tower	4,504
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	4,692
Pool/Patio Furniture Allowance (partial replacement)	4,692
Swimming Pool	
Filtration Equip Allowance (partial replacement)	4,692
Total for 2037 - 2038	\$293,992
	<i> </i>
Replacement Year 38-39	
Exterior Painting	
Painting - Pool Slide Stairs	6,151
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	4,856
Pool/Patio Furniture Allowance (partial replacement)	4,856
Sport Courts	
Sport Court Resurfacing (color coat)	39,159
Swimming Pool	
Filtration Equip Allowance (partial replacement)	4,856
Pool Resurfacing/Tile	190,423
Total for 2038 - 2039	\$250,302
Replacement Year 39-40	
-	
Furniture Fixtures & Equipment Ceiling Fans - Fitness Center	2,413
Fitness Equip. Allowance (partial replacement)	5,026
Pool/Patio Furniture Allowance (partial replacement)	5,026
	5,020
HVAC Equipment Air Handler (refurbished)	8,377
	0,377
Swimming Pool Filtration Equip Allowance (partial replacement)	5,026
Total for 2039 - 2040	\$25,867

Description	Expenditures
Replacement Year 40-41	
Misc. Site Components	
Monument Sign (Large) Refurbishment	6,936
Monument Sign (Small) Refurbishment	3,468
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	5,202
Pool/Patio Furniture Allowance (partial replacement)	5,202
Swimming Pool	
Filtration Equip Allowance (partial replacement)	5,202
Total for 2040 - 2041	\$26,010
Replacement Year 41-42	
Furniture Fixtures & Equipment	
Ceiling Fans - Family Gathering Room	2,584
Fitness Equip. Allowance (partial replacement)	5,384
Pool/Patio Furniture Allowance (partial replacement)	5,384
Swimming Pool	
Filtration Equip Allowance (partial replacement)	5,384
Total for 2041 - 2042	\$18,736
Replacement Year 42-43	
Fence & Gates	
Aluminum Gates/Fence- Entry	7,801
Site Lighting	
Light Fixtures - Concrete Poles	11,888
Flooring	
Wood Floor - Family Gathering Room	18,723
Furniture Fixtures & Equipment	
Access Control System	6,501
Fitness Equip. Allowance (partial replacement)	5,572
Pool/Patio Furniture Allowance (partial replacement)	5,572
Playground	
Playground Equipment Allowance	46,437
Swimming Pool	
Filtration Equip Allowance (partial replacement)	5,572


Community Advisors Page 4-7 March 23, 2024

Description	Expenditures
Replacement Year 42-43 continued	
Filtration System Refurishment Allowance	55,725
Total for 2042 - 2043	\$163,793
Replacement Year 43-44	
Exterior Painting	
Painting - Clubhouse Siding & Trim	32,683
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	5,768
Pool/Patio Furniture Allowance (partial replacement)	5,768
HVAC Equipment	15 200
HVAC Unit 2	15,380
Swimming Pool	5 7 6 9
Filtration Equip Allowance (partial replacement)	5,768
Total for 2043 - 2044	\$65,365
Replacement Year 44-45	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	5,969
Pool/Patio Furniture Allowance (partial replacement)	5,969
Swimming Pool	
Filtration Equip Allowance (partial replacement)	5,969
Pool Lift	11,226
Total for 2044 - 2045	\$29,134
Replacement Year 45-46	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	6,178
Pool/Patio Furniture Allowance (partial replacement)	6,178
Swimming Pool	
Filtration Equip Allowance (partial replacement)	6,178
Total for 2045 - 2046	\$18,535
Replacement Year 46-47	
Exterior Painting	
Painting - Pool Slide Stairs	8,100

Description	Expenditures
Replacement Year 46-47 continued	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	6,395
Pool/Patio Furniture Allowance (partial replacement)	6,395
HVAC Equipment	
HVAC Unit 1	17,905
Sport Courts	
Sport Court Resurfacing (color coat)	51,566
Swimming Pool	
Fiberglass Refurbish Allow - Pool Slide	61,814
Filtration Equip Allowance (partial replacement)	6,395
Refurbish Allowance - Pool Slide Frame	83,129
Total for 2046 - 2047	\$241,696
Replacement Year 47-48	
Fence & Gates	
Aluminum Fencing - Pool	164,956
Viny Ranch Fence - Tynes Blvd.	28,168
Parking Lots	
Asphalt Resurfacing - Phase II	102,571
Concrete Curbing Allow at Paving - Phase II	8,383
Cabinets & Tops	
Cabinets & Top - Outdoor Gathering	7,280
Furniture Fixtures & Equipment	
Fitness Equip. Replace Allowance	88,245
Pool/Patio Furniture Allowance (partial replacement)	6,618
Swimming Pool	
Concrete Pavers - Pool Deck/Patio	244,287
Filtration Equip Allowance (partial replacement)	6,618
Pool Splash Equipment Allowance	44,122
Shade Fabric - Pool	15,222
Splash Pad Equipment Allowance	92,657
Total for 2047 - 2048	\$809,128

	350 350 700
Fitness Equip. Allowance (partial replacement)6,8Pool/Patio Furniture Allowance (partial replacement)6,8	350
Fitness Equip. Allowance (partial replacement)6,8Pool/Patio Furniture Allowance (partial replacement)6,8	350
HVAC Fauinment	'00
	'00
HVAC Unit 3 A Condensor 13,7	
HVAC Unit 3 B Condensor 8,2	220
Sport Courts	
Shade Structure Replacement - Sport Courts 34,2	250
Swimming Pool	
	350
Total for 2048 - 2049 \$76,7	20
Replacement Year 49-50	
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)7,0)90
Furniture Allowance - Clubhouse 28,3	59
Office Furniture 4,7	26
Pool/Patio Furniture Allowance (partial replacement) 7,0)90
Life Safety Systems	
Fire Alarm Panel 16,0)70
Swimming Pool	
Filtration Equip Allowance (partial replacement) 7,0)90
Total for 2049 - 2050 \$70,4	25
Dords server t Veen 50 51	
Replacement Year 50-51	
Furniture Fixtures & Equipment	20
	338
	338
Swimming Pool	20
	338
Pool Resurfacing/Tile 287,7	
Total for 2050 - 2051 \$309,7	56

Description	Expenditures
Replacement Year 51-52	
Furniture Fixtures & Equipment	
Ceiling Fans - Exterior	15,797
Fitness Equip. Allowance (partial replacement)	7,595
Pool/Patio Furniture Allowance (partial replacement) Security Camera System Allowance	7,595 37,974
	57,974
Swimming Pool Filtration Equip Allowance (partial replacement)	7,595
Total for 2051 - 2052	
10tal 10r 2051 - 2052	\$76,555
Replacement Year 52-53	
Fence & Gates	
Chain Link Fence VC - Sport Courts	185,634
Misc. Building Components	
Exterior Door/Window Allowance (Partial Replace)	104,807
Furniture Fixtures & Equipment	
Fitness Equip. Allowance (partial replacement)	7,861
Pool/Patio Furniture Allowance (partial replacement)	7,861
Playground Wood Benches/Tables	12,577
	12,377
Sport Courts Drinking Fountain	12,577
Sport Court Replacement	505,117
Swimming Pool	,
Filtration Equip Allowance (partial replacement)	7,861
Total for 2052 - 2053	\$844,293
Replacement Year 53-54	
Exterior Painting	46 100
Painting - Clubhouse Siding & Trim	46,102
Furniture Fixtures & Equipment Fitness Equip. Allowance (partial replacement)	8,136
Pool/Patio Furniture Allowance (partial replacement)	8,136
Swimming Pool	0,150
Filtration Equip Allowance (partial replacement)	8,136
Total for 2053 - 2054	\$70,509
	ΨΓΟ,ΟΟΣ



Community Advisors Page 4-12 March 23, 2024

			<i>i</i> t		*	<u>^</u>		
	· 4 · .			× .	and in site	. Singo	, v	
Description	Sec. Construction	200 20	\$ 50	Agi	to man and the second	Jit	JAN CON	Carlotte Cost
Misc. Site Components								
Monument Sign (Large) Refurbishment Monument Sign (Small) Refurbishment	2008 2008	25-26 25-26	15 15	3 3	1 1	1 Lump Sum 1 Lump Sum	4,000.00 2,000.00	4,000 _2,000
Misc. Site Components - Total	2008	23-20	15	3	1	1 Lump Sum	2,000.00	\$6,000
Fence & Gates								
Aluminum Fencing - Pool	2023	47-48	25	0	23	804 Linear Feet	93.00	74,772
Aluminum Gates/Fence- Entry	2023	42-43	20	0	18	1 Lump Sum	4,200.00	4,200
Chain Link Fence VC - Sport Courts	2023	52-53	30	0	28	738 Linear Feet	96.00	70,848
Chain Link Fence/Gates - Dumpster	2008	32-33	25	0	8	48 Linear Feet	48.00	2,304
Viny Ranch Fence - Tynes Blvd.	2023	47-48	25	0	23	304 Linear Feet	42.00	12,768
Vinyl Fencing - Pine Ridge Pkwy	2008	32-33	25	0	8	82 Linear Feet	32.00	2,624
Fence & Gates - Total								\$167,516
Parking Lots								
Asphalt Resurfacing - Phase I	2008	32-33	25	0	8	2,400 Square Yards	21.00	50,400
Asphalt Resurfacing - Phase II	2023	47-48	25	0	23	2,214 Square Yards	21.00	46,494
Concrete Curbing Allow at Paving - Phase I	2008	32-33	25	0	8	100 Linear Feet	38.00	3,800
Concrete Curbing Allow at Paving - Phase II	2023	47-48	25	0	23	100 Linear Feet	38.00	3,800
Parking Lots - Total								\$104,494
Site Lighting								
Decorative Light Poles - Parking Lot	2008	32-33	25	0	8	6 Each	2,800.00	16,800
Decorative Light Poles - Playgound/Trail	2008	32-33	25	0	8	10 Each	2,800.00	28,000
Decorative Light Poles - Pool	2008	32-33	25	0	8	8 Each	3,900.00	31,200
Light Fixtures - Concrete Poles	2023	42-43	20	0	18	8 Each	800.00	6,400
Site Lighting - Total								\$82,400
Misc. Building Components								
Exterior Door/Window Allowance (Partial R	2008	52-53	45	0	28	1 Lump Sum	40,000.00	40,000
Folding Partition - Meeting Room	2008	37-38	30	0	13	13 Linear Feet	220.00	2,860
Refurbish Allowance - Clubhouse Restrooms	2008	34-35	25	2	10	260 Square Feet	128.00	33,280
Refurbish Allowance - Locker Rooms	2008	34-35	25	2	10	814 Square Feet	128.00	_104,192
Misc. Building Components - Total								\$180,332
Roofing								
Metal Roof - Clubhouse	2008	37-38	30	0	13	12,200 Square Feet	14.20	173,240
Metal Roof - Pool Slide Tower	2008	37-38	30	0	13	80 Square Feet	36.00	2,880
Roofing - Total								\$176,120
Cabinets & Tops								
Cabinets & Top - Outdoor Gathering	2008	27-28	20	0	3	15 Linear Feet	220.00	3,300
Cabinets & Tops - Meeting Area	2008	32-33	25	0	8	14 Linear Feet	320.00	4,480
Cabinets & Tops - Serving Room	2008	32-33	25	0	8	29 Linear Feet	320.00	9,280
Cabinets & Tops - Total								\$17,060

Community Advisors Page 5-1 March 23, 2024

			and the second s		10	<i>م</i> ہ		
Description	Day Sold	Co Co Co Co	2 23 23 20 23 20 20		Ponoit in	15 ANS	JAN COST	Catelon Case
Description	\checkmark $\stackrel{\sim}{\rightarrow}$	$\sim \sim$	\sim	Υ.	\sim	\sim	\sim U	00
Exterior Painting								
Painting - Clubhouse Siding & Trim	2024	33-34	10	0	9	1 Lump Sum	17,000.00	17,000
Painting - Pool Slide Stairs	2023	30-31	8	0	6	1 Lump Sum	3,800.00	$\frac{3,800}{\$20,800}$
Exterior Painting - Total								\$20,800
Flooring								
Carpet - Clubhouse (replace with vinyl)	2008	24-25	8	0	0	450 Square Feet	8.40	3,780
Rubber Floor - Fitness Room	2008	32-33	25	0	8	76 Square Yards	58.00	4,408
Tile Floor - Serving Room	2008	32-33	25	0	8	260 Square Feet	12.75	3,315
Vinyl Plank Floor - Activity Room/Corridor	2008	32-33	25	0	8	685 Square Feet	8.40	5,754
Wood Floor - Family Gathering Room	2008	42-43	35	0	18	840 Square Feet	12.00	10,080
Flooring - Total								\$27,337
Eumiture Eistures & Equipment								
Furniture Fixtures & Equipment Access Control System	2008	27-28	15	5	3	1 Lump Sum	3,500.00	2 500
Ceiling Fans - Exterior	2008	27-28 36-37	15	0	12	13 Each	480.00	3,500 6,240
Ceiling Fans - Family Gathering Room	2022	41-42	20	0	12	3 Each	480.00	1,440
Ceiling Fans - Fitness Center	2022	39-40	20 15	3	15	3 Each	480.00	1,440
Fitness Equip. Allowance (partial replaceme		24-25	13	0	0	1 Lump Sum	3,000.00	3,000
Fitness Equip. Replace Allowance	2008	47-48	40	0	23	1 Lump Sum	40,000.00	40,000
Furniture Allowance - Clubhouse	2008	29-30	20	2	5	1 Lump Sum	12,000.00	12,000
Office Furniture	2008	29-30	20	2	5	1 Lump Sum	2,000.00	2,000
Pool/Patio Furniture Allowance (partial repl		24-25	1	0	0	1 Lump Sum	3,000.00	3,000
Pool/Patio Furniture Replacement Allowance		32-33	25	0	8	1 Lump Sum	42,000.00	42,000
Security Camera System Allowance	2022	36-37	15	0	12	1 Lump Sum	15,000.00	15,000
Furniture Fixtures & Equipment - Total						Ĩ	,	\$129,620
HVAC Equipment								
Air Handler (refurbished)	2019	39-40	20	0	15	1 Lump Sum	5,000.00	5,000
HVAC Unit 1	2023	34-35	12	0	10	7 Tons	1,200.00	8,400
HVAC Unit 2	2019	31-32	12	0	7	5 Tons	1,600.00	8,000
HVAC Unit 3 A Condensor	2008	24-25	12	0	0	5 Tons	1,200.00	6,000
HVAC Unit 3 B Condensor	2008	24-25	12	0	0	3 Tons	1,200.00	3,600
HVAC Equipment - Total								\$31,000
Life Safety Systems								
Fire Alarm Panel	2008	29-30	20	2	5	1 Lump Sum	6,800.00	6,800
Life Safety Systems - Total	2000	27 30	20	2	5	1 Lump Sum	0,000.00	\$6,800
								+ • , • • •
Playground								
Playground Equipment Allowance	2013	27-28	15	0	3	1 Lump Sum	25,000.00	25,000
Wood Benches/Tables	2013	32-33	20	0	8	4 Each	1,200.00	4,800
Playground - Total								\$29,800

			and the second		-Th			
Description	Das Service	2 2 0 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	100 100 100 100 100 100 100 100 100 100	Adi.	A Contraction of the second	in Jains	State Cost	Children Contraction
Sport Courts								
Drinking Fountain	2023	52-53	30	0	28	1 Each	4,800.00	4,800
Shade Fabric - Sport Courts	2023	36-37	14	0	12	1 Each	2,300.00	2,300
Shade Structure Replacement - Sport Courts	2023	48-49	26	0	24	1 Each	15,000.00	15,000
Sport Court Replacement	2023	52-53	30	0	28	2,520 Square Yards	76.50	192,780
Sport Court Resurfacing (color coat)	2023	30-31	8	0	6	2,520 Square Yards	9.60	24,192
Sport Courts - Total								\$239,072
Swimming Pool								
Concrete Pavers - Pool Deck/Patio	2008	47-48	40	0	23	14,570 Square Feet	7.60	110,732
Fiberglass Refurbish Allow - Pool Slide	2023	34-35	12	0	10	1 Lump Sum	29,000.00	29,000
Filtration Equip Allowance (partial replace	2008	24-25	1	0	0	1 Lump Sum	3,000.00	3,000
Filtration System Refurishment Allowance	2008	42-43	35	0	18	1 Lump Sum	30,000.00	30,000
Pool Lift	2021	32-33	12	0	8	1 Each	5,642.00	5,642
Pool Resurfacing/Tile	2015	26-27	12	0	2	3,460 Square Feet	34.00	117,640
Pool Splash Equipment Allowance	2008	27-28	20	0	3	1 Lump Sum	20,000.00	20,000
Refurbish Allowance - Pool Slide Frame	2023	34-35	12	0	10	1 Lump Sum	39,000.00	39,000
Shade Fabric - Pool	2024	47-48	14	10	23	3 Each	2,300.00	6,900
Shade Structure Replacement	2008	33-34	26	0	9	3 Each	15,000.00	45,000
Splash Pad Equipment Allowance	2023	47-48	25	0	23	1 Lump Sum	42,000.00	42,000
Swimming Pool - Total								\$448,914

Operating Expense

Backflow Preventer Repair	Unfunded
Electrical Panels/Disconnects	Unfunded
Fire Detection Devices	Unfunded
Flag Pole	Unfunded
Grills	Unfunded
Interior Painting - Clubhouse	Unfunded
Laminated Beam Repair	Unfunded
Message Board	Unfunded
Painting - Entry Features	Unfunded
Painting - Pool Equipment Yard	Unfunded
Pendent Lights - Breezeway	Unfunded
Refrigerator	Unfunded
Splash Pad Coating/Repair	Unfunded
Sport Court Nets/Equipment	Unfunded
Trash Cans/ Misc. Site Furnishings	Unfunded
Water Coolers - Clubhouse	Unfunded
Water Heater - Clubhouse	Unfunded
Operating Expense - Total	

Components Not Included

Backflow Preventer Replacement Building Foundation/Frame Unfunded Unfunded

> Community Advisors Page 5-3 March 23, 2024

Active Sector Sector Alter Activities Ore series Jais

تأثث للأثري



Description

Components Not Included continued... Communication Wiring/Devices in Building Electrical Wiring/Devices in Building Light Poles (Concrete) - Parking Lot Siding/Trim Replacement Site Utilities Water/Sewer/Vent Piping In building Components Not Included - Total

Unfunded Unfunded Unfunded Unfunded Unfunded

Unfunded

Components Removed

Wood Pergolas - Entry Signs Components Removed - Total

Total Asset Summary

\$1,667,265

Community Advisors Page 5-4 March 23, 2024

Asset II	DDescription	Replacement	Page
Misc. S	ite Components		
1005	Monument Sign (Large) Refurbishment	25-26	5-9
1006	Monument Sign (Small) Refurbishment	25-26	5-9
Fence &	& Gates		
1047	Aluminum Fencing - Pool	47-48	5-11
1049	Aluminum Gates/Fence- Entry	42-43	5-11
	Chain Link Fence VC - Sport Courts	52-53	5-12
1051	Chain Link Fence/Gates - Dumpster	32-33	5-12
1048	Viny Ranch Fence - Tynes Blvd.	47-48	5-13
1050	Vinyl Fencing - Pine Ridge Pkwy	32-33	5-13
Parking	g Lots		
1001	Asphalt Resurfacing - Phase I	32-33	5-14
1001	Asphalt Resurfacing - Phase II	47-48	5-14
1002	Concrete Curbing Allow at Paving - Phase I	32-33	5-15
1002	Concrete Curbing Allow at Paving - Phase II	47-48	5-15
Site Lig	ghting		
1070	Decorative Light Poles - Parking Lot	32-33	5-16
1062	Decorative Light Poles - Playgound/Trail	32-33	5-16
1069	Decorative Light Poles - Pool	32-33	5-17
1071	Light Fixtures - Concrete Poles	42-43	5-17
Misc. B	Building Components		
	Exterior Door/Window Allowance (Partial Replace)	52-53	5-18
1013	Folding Partition - Meeting Room	37-38	5-18
	Refurbish Allowance - Clubhouse Restrooms	34-35	5-19
	Refurbish Allowance - Locker Rooms	34-35	5-19
Roofing			
1073	Metal Roof - Clubhouse	37-38	5-21
1072	Metal Roof - Pool Slide Tower	37-38	5-21
Cabine	ts & Tops		
1089	Cabinets & Top - Outdoor Gathering	27-28	5-23
1085	Cabinets & Tops - Meeting Area	32-33	5-23
1086	Cabinets & Tops - Serving Room	32-33	5-24
		- •	

Asset I	DDescription	Replacement	Page
Exterio	or Painting		
1075	Painting - Clubhouse Siding & Trim	33-34	5-25
1077	Painting - Pool Slide Stairs	30-31	5-25
Floorin	ıg		
1040	Carpet - Clubhouse (replace with vinyl)	24-25	5-26
1041	Rubber Floor - Fitness Room	32-33	5-26
1045	Tile Floor - Serving Room	32-33	5-27
1043	Vinyl Plank Floor - Activity Room/Corridor	32-33	5-27
1044	Wood Floor - Family Gathering Room	42-43	5-27
Furnit	ure Fixtures & Equipment		
1065	Access Control System	27-28	5-29
1064	Ceiling Fans - Exterior	36-37	5-29
1067	Ceiling Fans - Family Gathering Room	41-42	5-29
1063	Ceiling Fans - Fitness Center	39-40	5-30
1029	Fitness Equip. Allowance (partial replacement)	24-25	5-30
1029	Fitness Equip. Replace Allowance	47-48	5-31
	Furniture Allowance - Clubhouse	29-30	5-32
1028	Office Furniture	29-30	5-32
1030	Pool/Patio Furniture Allowance (partial replacement)	24-25	5-33
1030	Pool/Patio Furniture Replacement Allowance	32-33	5-33
1066	Security Camera System Allowance	36-37	5-34
HVAC	Equipment		
1059	Air Handler (refurbished)	39-40	5-35
1061	HVAC Unit 1	34-35	5-35
1060	HVAC Unit 2	31-32	5-36
1060	HVAC Unit 3 A Condensor	24-25	5-36
1060	HVAC Unit 3 B Condensor	24-25	5-36
Life Sa	fety Systems		
1068	Fire Alarm Panel	29-30	5-37
Playgro	ound		
1036	Playground Equipment Allowance	27-28	5-38
1035	Wood Benches/Tables	32-33	5-38

Asset I	DDescription	Replacement	Page
Sport (Courts		
•	Drinking Fountain	52-53	5-39
1022	Shade Fabric - Sport Courts	36-37	5-39
	Shade Structure Replacement - Sport Courts	48-49	5-40
	Sport Court Replacement	52-53	5-40
	Sport Court Resurfacing (color coat)	30-31	5-41
Swimn	ning Pool		
	Concrete Pavers - Pool Deck/Patio	47-48	5-42
1020	Fiberglass Refurbish Allow - Pool Slide	34-35	5-42
1020	Filtration Equip Allowance (partial replacement)	24-25	5-43
1025	Filtration System Refurishment Allowance	42-43	5-43
1025	Pool Lift	32-33	5-44
1021	Pool Resurfacing/Tile	26-27	5-44
1010	Pool Splash Equipment Allowance	27-28	5-45
1017	Refurbish Allowance - Pool Slide Frame	34-35	5-45
1022	Shade Fabric - Pool	47-48	5-46
1022	Shade Structure Replacement	33-34	5-46
1020	Splash Pad Equipment Allowance	47-48	5-47
Onorat	ting Expense		
Operat	Backflow Preventer Repair	24-25	5-48
	Electrical Panels/Disconnects	24-25	5-48
1071	Fire Detection Devices	24-25	5-49
1071	Flag Pole	24-25	5-49
	Grills	24-25	5-49
1074	Interior Painting - Clubhouse	24-25	5-50
1074	Laminated Beam Repair	24-25	5-50
	Message Board	24-25	5-51
1081	Painting - Entry Features	24-25	5-51
1078	Painting - Pool Equipment Yard	24-25	5-51
1070	Pendent Lights - Breezeway	24-25	5-52
1034	Refrigerator	24-25	5-52
1007	Splash Pad Coating/Repair	24-25	5-52 5-53
	Sport Court Nets/Equipment	24-25	5-53
	Trash Cans/ Misc. Site Furnishings	24-25	5-54
1053	Water Coolers - Clubhouse	24-25	5-54
1055	Water Heater - Clubhouse	24-25	5-55

Asset I	DDescription	Replacement	Page
Compo	onents Not Included		
	Backflow Preventer Replacement	24-25	5-56
1071	Building Foundation/Frame	24-25	5-56
1071	Communication Wiring/Devices in Building	24-25	5-56
1071	Electrical Wiring/Devices in Building	24-25	5-57
1071	Light Poles (Concrete) - Parking Lot	24-25	5-57
1071	Siding/Trim Replacement	24-25	5-57
1071	Site Utilities	24-25	5-58
1071	Water/Sewer/Vent Piping In building	24-25	5-58
Compo	onents Removed		
1004	Wood Pergolas - Entry Signs	24-25	5-59
	Total Funded Assets	67	
	Total Unfunded Assets	<u>26</u>	
	Total Assets	93	

Monument Sign (Large) I	Refurbishment - 202	25	
Asset ID	1005	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$4,000.00 \$4,000.00 100%
Category Misc.	Site Components	Future Cost	\$4,140.00
Placed in Service	June 2008		
Useful Life	15		
Adjustment	3		
Replacement Year	25-26		
Remaining Life	1		
	1 Au	THE REPORT OF A DESCRIPTION OF A DESCRIPTION	



Monument Sign (Small) Refurbishment - 2025

Asset ID	1006
Category Misc. Si	ite Components
Placed in Service	June 2008
Useful Life	15
Adjustment	3
Replacement Year	25-26
Remaining Life	1

1 Lump Sum	@ \$2,000.00
Asset Actual Cost	\$2,000.00
Percent Replacement	100%
Future Cost	\$2,070.00

Monument Sign (Small) Refurbishment continued...



Community Advisors Page 5-10 March 23, 2024

Aluminum Fencing - I	Pool - 2047	804 Linear Feet	@ \$93.00
Asset ID	1047	Asset Actual Cost	\$74,772.00
		Percent Replacement	100%
Category	Fence & Gates	Future Cost	\$164,955.59
Placed in Service	March 2023		
Useful Life	25		
Replacement Year	47-48		
Remaining Life	23		

Aluminum Gates/Fence- Entry - 2042

Asset ID	
Category	
Placed in Service	
Useful Life	
Replacement Year	
Remaining Life	

1049
Fence & Gates
June 2023
20
42-43
18

1 Lump Sum	@ \$4,200.00
Asset Actual Cost	\$4,200.00
Percent Replacement	100%
Future Cost	\$7,801.45



Community Advisors Page 5-11 March 23, 2024

Chain Link Fence VC - Sport Courts - 2052

Asset ID

Category
Placed in Service
Useful Life
Replacement Year
Remaining Life

Fence & Gates
June 2023
30
52-53
28

738 Linear Feet@ \$96.00Asset Actual Cost\$70,848.00Percent Replacement100%Future Cost\$185,633.94



Chain Link Fence/Gates - Dumpster - 2032

Category
Placed in Service
Useful Life
Replacement Year
Remaining Life

Asset ID

Fence & Gates June 2008 25 32-33 8

1051

@ \$48.00
\$2,304.00
100%
\$3,033.93



Community Advisors Page 5-12 March 23, 2024

Viny Ranch Fence - Tynes Blvd. - 2047

Asset ID	1048
Category	Fence & Gates
Placed in Service	March 2023
Useful Life	25
Replacement Year	47-48
Remaining Life	23

304 Linear Feet	@ \$42.00
Asset Actual Cost	\$12,768.00
Percent Replacement	100%
Future Cost	\$28,167.67



Vinyl Fencing - Pine Ridge Pkwy - 2032

Asset ID	1050	82 Linear Feet Asset Actual Cost Percent Replacement	@ \$32.00 \$2,624.00 100%
Category	Fence & Gates	Future Cost	\$3,455.31
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Community Advisors Page 5-13 March 23, 2024

Asphalt Resurfacing - Phase I - 2032	Asphalt	Resurfacing	- Phase]	[- 2032
--------------------------------------	---------	-------------	-----------	----------

Asset ID 1001

Category Placed in Service Useful Life Replacement Year Remaining Life

1001
Parking Lots
June 2008
25
32-33
8

2,400 Square Yards	@ \$21.00
Asset Actual Cost	\$50,400.00
Percent Replacement	100%
Future Cost	\$66,367.18



Asphalt Resurfacing - Phase II - 2047

Asset ID	1001
Category	Parking Lots
Placed in Service	June 2023
Useful Life	25
Replacement Year	47-48
Remaining Life	23

@ \$21.00
\$46,494.00
100%
\$102,571.09



Community Advisors Page 5-14 March 23, 2024

Concrete Curbing Allow	at Paving - Phase I	- 2032	
Asset ID	1002	100 Linear Feet Asset Actual Cost Percent Replacement	@ \$38.00 \$3,800.00 100%
Category	Parking Lots	Future Cost	\$5,003.87
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		
		and the fact of the second	



Concrete Curbing Allow at Paving - Phase II - 2047

		100 Linear Feet	@ \$38.00
Asset ID	1002	Asset Actual Cost	\$3,800.00
		Percent Replacement	100%
Category	Parking Lots	Future Cost	\$8,383.23
Placed in Service	June 2023		
Useful Life	25		
Replacement Year	47-48		
Remaining Life	23		



Community Advisors Page 5-15 March 23, 2024

Decorative Light Poles	- Parking Lot - 2032		
		6 Each	@ \$2,800.00
Asset ID	1070	Asset Actual Cost	\$16,800.00
		Percent Replacement	100%
Category	Site Lighting	Future Cost	\$22,122.39
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Decorative Light Poles - Playgound/Trail - 2032

Asset ID	1062	10 Each Asset Actual Cost Percent Replacement	@ \$2,800.00 \$28,000.00 100%
Category	Site Lighting	Future Cost	\$36,870.65
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Community Advisors Page 5-16 March 23, 2024

Decorative Light Poles	- Pool - 2032	8 Each	@ \$3,900.00
Asset ID	1069	Asset Actual Cost	\$31,200.00
		Percent Replacement	100%
Category	Site Lighting	Future Cost	\$41,084.44
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Light Fixtures - Concret	e Poles - 2042	8 Each	@ \$800.00
Asset ID	1071	Asset Actual Cost	\$6,400.00
		Percent Replacement	100%
Category	Site Lighting	Future Cost	\$11,887.93
Placed in Service	June 2023		
Useful Life	20		
Replacement Year	42-43		
Remaining Life	18		



Community Advisors Page 5-17 March 23, 2024

Exterior Door/Window Allowance (Partial Replace) - 2052

Asset	ID

Categorisc. Building Components		
Placed in Service	June 2008	
Useful Life	45	
Replacement Year	52-53	
Remaining Life	28	

 1 Lump Sum
 @ \$40,000.00

 Asset Actual Cost
 \$40,000.00

 Percent Replacement
 100%

 Future Cost
 \$104,806.88



Folding Partition - Meeting Room - 2037

Asset ID	1013
Categvisc. Buildi	ing Components
Placed in Service	June 2008
Useful Life	30
Replacement Year	37-38
Remaining Life	13

@ \$220.00
\$2,860.00
100%
\$4,472.91

Refurbish Allowance - C	lubhouse Restroom	s - 2034	
		260 Square Feet	@ \$128.00
Asset ID		Asset Actual Cost	\$33,280.00
		Percent Replacement	100%
Categorisc. Build	ding Components	Future Cost	\$46,944.73
Placed in Service	June 2008		
Useful Life	25		
Adjustment	2		
Replacement Year	34-35		
Remaining Life	10		



Refurbish Allowance - Locker Rooms - 2034

Remaining Life

Asset ID		814 Square Feet Asset Actual Cost Percent Replacement	@ \$128.00 \$104,192.00 100%
Categolisc.	Building Components	Future Cost	\$146,973.11
Placed in Service	June 2008		
Useful Life	25		
Adjustment	2		
Replacement Year	34-35		

10

Refurbish Allowance - Locker Rooms continued...



Community Advisors Page 5-20 March 23, 2024

37	12,200 Square Feet	@ \$14.20
1073	Asset Actual Cost	\$173,240.00
	Percent Replacement	100%
Roofing	Future Cost	\$270,939.75
June 2008		
30		
37-38		
13		
	1073 Roofing June 2008 30 37-38	1073Asset Actual Cost Percent ReplacementRoofingFuture CostJune 20083037-38State



Metal is discolored from previous cleaning. Recommend inspection, cleaning and repair as needed.

Metal Roof - Pool Slide T	Cower - 2037		
Asset ID	1072	80 Square Feet Asset Actual Cost Percent Replacement	@ \$36.00 \$2,880.00 100%
Category	Roofing	Future Cost	\$4,504.19
Placed in Service	June 2008		
Useful Life	30		
Replacement Year	37-38		
Remaining Life	13		

Metal Roof - Pool Slide Tower continued...



Community Advisors Page 5-22 March 23, 2024

Cabinets & Top - Outdoor Gathering - 2027

Asset ID	1089
Category	Cabinets & Tops
Placed in Service	June 2008
Useful Life	20
Replacement Year	27-28
Remaining Life	3

15 Linear Feet	@ \$220.00
Asset Actual Cost	\$3,300.00
Percent Replacement	100%
Future Cost	\$3,658.77



Cabinets & Tops - Meeting Area - 2032

Category
Placed in Service
Useful Life
Replacement Year
Remaining Life

Asset ID

Calinata 8 Tana
Cabinets & Tops
June 2008
25
32-33
8

1085

14 Linear Feet	@ \$320.00
Asset Actual Cost	\$4,480.00
Percent Replacement	100%
Future Cost	\$5,899.30



Community Advisors Page 5-23 March 23, 2024

1086

Cabinets & Tops - Serving Room - 2032

Asset ID

Category Placed in Service Useful Life Replacement Year Remaining Life

Cabinets & Tops
June 2008
25
32-33
8

29 Linear Feet@ \$320.00Asset Actual Cost\$9,280.00Percent Replacement100%Future Cost\$12,219.99



Community Advisors Page 5-24 March 23, 2024

Painting - Clubhouse S	Siding & Trim - 2033	ļ	
		1 Lump Sum	@ \$17,000.00
Asset ID	1075	Asset Actual Cost	\$17,000.00
		Percent Replacement	100%
Category	Exterior Painting	Future Cost	\$23,169.25
Placed in Service	March 2024		
Useful Life	10		
Replacement Year	33-34		
Remaining Life	9		



1 Lump	Stairs - 2030	Painting - Pool Slide S
Asset Actual	1077	Asset ID
Percent Replace		
Future	Exterior Painting	Category
	March 2023	Placed in Service
	8	Useful Life
	30-31	Replacement Year
	6	Remaining Life

@ \$3,800.00
\$3,800.00
100%
\$4,671.17



Community Advisors Page 5-25 March 23, 2024

e with vinyl) - 202	24	
1040	450 Square Feet Asset Actual Cost Percent Replacement	@ \$8.40 \$3,780.00 100%
Flooring	Future Cost	\$3,780.00
June 2008		
8		
24-25		
0		
	1040 Flooring June 2008 8 24-25	1040Asset Actual CostPercent ReplacementFlooringJune 2008824-25



Rubber Floor - Fitness Room - 2032

Asset ID	1041	76 Square Yards Asset Actual Cost Percent Replacement	@ \$58.00 \$4,408.00 100%
Category	Flooring	Future Cost	\$5,804.49
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Community Advisors Page 5-26 March 23, 2024

Tile Floor - Serving Room	n - 2032	260 Square Feet	@ \$12.75
Asset ID	1045	Asset Actual Cost	\$3,315.00
		Percent Replacement	100%
Category	Flooring	Future Cost	\$4,365.22
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		

Vinyl Plank Floor - Activity Room/Corridor - 2032

		685 Square Feet	@ \$8.40
Asset ID	1043	Asset Actual Cost	\$5,754.00
		Percent Replacement	100%
Category	Flooring	Future Cost	\$7,576.92
Placed in Service	June 2008		
Useful Life	25		
Replacement Year	32-33		
Remaining Life	8		



Wood Floor - Family Gathering Room - 2042

Asset ID	1044	840 Square Feet Asset Actual Cost Percent Replacement	@ \$12.00 \$10,080.00 100%
Category	Flooring	Future Cost	\$18,723.49
Placed in Service	June 2008		
Useful Life	35		
Replacement Year	42-43		
Remaining Life	18		

Community Advisors Page 5-27 March 23, 2024

Wood Floor - Family Gathering Room continued...



Community Advisors Page 5-28 March 23, 2024

Access Control System - 2027		1 Lump Sum	@ \$3,500.00
Asset ID	1065	Asset Actual Cost	\$3,500.00
		Percent Replacement	100%
Gategiourye Fixtures & Ec	quipment	Future Cost	\$3,880.51
Placed in Service Ju	ine 2008		
Useful Life	15		
Adjustment	5		
Replacement Year	27-28		
Remaining Life	3		

Ceiling Fans - Exterior - 203	36
Asset ID	1064
Gategiouy e Fixtures Placed in Service Useful Life Replacement Year Remaining Life	& Equipment June 2022 15 36-37 12

13 Each	@ \$480.00
Asset Actual Cost	\$6,240.00
Percent Replacement	100%
Future Cost	\$9,429.07



Ceiling Fans - Family Gathering Room - 2041

Asset ID	1067
Gategiouy e Fixtures	s & Equipment
Placed in Service	June 2022
Useful Life	20
Replacement Year	41-42
Remaining Life	17

3 Each	@ \$480.00
Asset Actual Cost	\$1,440.00
Percent Replacement	100%
Future Cost	\$2,584.33

Ceiling Fans - Family Gathering Room continued...



Ceiling Fans - Fitness Cer	nter - 2039	3 Each	@ \$480.00
Asset ID	1063	Asset Actual Cost	\$1,440.00
		Percent Replacement	100%
Gategiouy e Fixtu	res & Equipment	Future Cost	\$2,412.50
Placed in Service	June 2022		
Useful Life	15		
Adjustment	3		
Replacement Year	39-40		
Remaining Life	15		

Fitness Equip. Allowance (partial replacement) - 2024

		1 Lump Sum	@ \$3,000.00
Asset ID	1029	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Gategiouye Fixtures & Equipment		Future Cost	\$3,000.00
Placed in Service	June 2008		
Useful Life	1		
Replacement Year	24-25		
Remaining Life	0		

Fitness Equip. Allowance (partial replacement) continued...



Fitness Equip. Replace Allowance - 2047

Asset ID	1029
Gategiouse Fixtures	& Equipment
Placed in Service	June 2008
Useful Life	40
Replacement Year	47-48
Remaining Life	23

@ \$40,000.00
\$40,000.00
100%
\$88,244.58



Furniture Allowance - Clubhouse - 2029

Asset ID

Gategiourye Fixtures & Equipment			
Placed in Service	June 2008		
Useful Life	20		
Adjustment	2		
Replacement Year	29-30		
Remaining Life	5		

 1 Lump Sum
 @ \$12,000.00

 Asset Actual Cost
 \$12,000.00

 Percent Replacement
 100%

 Future Cost
 \$14,252.24



Office Furniture - 2029		1 Lump Sum	@ \$2,000.00
Asset ID	1028	Asset Actual Cost	\$2,000.00
		Percent Replacement	100%
Chatengiourye Fixtu	res & Equipment	Future Cost	\$2,375.37
Placed in Service	June 2008		
Useful Life	20		
Adjustment	2		
Replacement Year	29-30		
Remaining Life	5		

Pool/Patio Furniture	Allowance (partial rej	placement) - 2024	
		1 Lump Sum	@ \$3,000.00
Asset ID	1030	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Gategiourye	Fixtures & Equipment	Future Cost	\$3,000.00
Placed in Service	June 2008		
Useful Life	1		
Replacement Year	24-25		
Remaining Life	0		

Pool/Patio Furniture Replacement Allowance - 2032	
1 001/1 atto 1 armaice Replacement 7 mowanee - 2052	

Asset ID	1030	1 Lump Sum Asset Actual Cost	@ \$42,000.00 \$42,000.00 100%
Categiouye Fixtures & Equipment		Percent Replacement Future Cost	\$55,305.98
Placed in Service Useful Life	June 2008 25		
Replacement Year	32-33		
Remaining Life	8		



Community Advisors Page 5-33 March 23, 2024

Security Camera System	Allowance - 2036		
Asset ID	1066	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$15,000.00 \$15,000.00 100%
Gategiouy e Fixtu	ures & Equipment	Future Cost	\$22,666.03
Placed in Service	August 2022		
Useful Life	15		
Replacement Year	36-37		
Remaining Life	12		

Community Advisors Page 5-34 March 23, 2024

Air Handler (refurbish	ned) - 2039	1 Lump Sum	@ \$5,000.00
Asset ID	1059	Asset Actual Cost	\$5,000.00
		Percent Replacement	100%
Category	HVAC Equipment	Future Cost	\$8,376.74
Placed in Service	November 2019		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	15		



HVAC Unit 1 - 2034		7 Tons	@ \$1,200.00
Asset ID	1061	Asset Actual Cost	\$8,400.00
		Percent Replacement	100%
Category	HVAC Equipment	Future Cost	\$11,849.03
Placed in Service	July 2023		
Useful Life	12		
Replacement Year	34-35		
Remaining Life	10		



Community Advisors Page 5-35 March 23, 2024

HVAC Unit 2 - 2031	J	5 Tons	@ \$1,600.00
Asset ID	1060	Asset Actual Cost	\$8,000.00
		Percent Replacement	100%
Category	HVAC Equipment	Future Cost	\$10,178.23
Placed in Service	November 2019		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	7		



HVAC Unit 3 A Cond	lensor - 2024	5 Tons	@ \$1,200.00
Asset ID	1060	Asset Actual Cost	\$6,000.00
		Percent Replacement	100%
Category	HVAC Equipment	Future Cost	\$6,000.00
Placed in Service	December 2008		
Useful Life	12		
Replacement Year	24-25		
Remaining Life	0		

HVAC Unit 3 B Condensor - 2024			
Asset ID	1060		
Category Placed in Service Useful Life Replacement Year Remaining Life	HVAC Equipment December 2008 12 24-25 0		

3 Tons	@ \$1,200.00
Asset Actual Cost	\$3,600.00
Percent Replacement	100%
Future Cost	\$3,600.00

Fire Alarm Panel - 202	9	1 Lump Sum	@ \$6,800.00
Asset ID	1068	Asset Actual Cost	\$6,800.00
		Percent Replacement	100%
Category	Life Safety Systems	Future Cost	\$8,076.27
Placed in Service	June 2008		
Useful Life	20		
Adjustment	2		
Replacement Year	29-30		
Remaining Life	5		



Community Advisors Page 5-37 March 23, 2024

Playground Equipment Allowance - 1	2027
------------------------------------	------

Asset ID	1036
Category	Playground
Placed in Service	June 2013
Useful Life	15
Replacement Year	27-28
Remaining Life	3

1 Lump Sum	@ \$25,000.00
Asset Actual Cost	\$25,000.00
Percent Replacement	100%
Future Cost	\$27,717.95



Wood Benches/Tables - 2	2032	
Asset ID	1035	
		Pe
Category	Playground	
Placed in Service	June 2013	
Useful Life	20	
Replacement Year	32-33	
Remaining Life	8	

4 Each	@ \$1,200.00
Asset Actual Cost	\$4,800.00
Percent Replacement	100%
Future Cost	\$6,320.68



Community Advisors Page 5-38 March 23, 2024

Drinking Fountain - 2052		1 Each	@ \$4,800.00
Asset ID		Asset Actual Cost	\$4,800.00
		Percent Replacement	100%
Category	Sport Courts	Future Cost	\$12,576.82
Placed in Service	March 2023		
Useful Life	30		
Replacement Year	52-53		
Remaining Life	28		



Shade Fabric - Sport Co	urts - 2036	1 Each	@ \$2,300.00
Asset ID	1022	Asset Actual Cost	\$2,300.00
		Percent Replacement	100%
Category	Sport Courts	Future Cost	\$3,475.46
Placed in Service	March 2023		
Useful Life	14		
Replacement Year	36-37		
Remaining Life	12		



Shade fabric scheduled for replacement in FY 2036 as a one time replacement. The next cycle

Community Advisors Page 5-39 March 23, 2024

Shade Fabric - Sport Courts continued...

of fabric replacement projected to occur in FY 2048 at time of frame and fabric replacement.

Shade Structure Replace	ement - Sport Courts	- 2048	
		1 Each	@ \$15,000.00
Asset ID		Asset Actual Cost	\$15,000.00
		Percent Replacement	100%
Category	Sport Courts	Future Cost	\$34,249.93
Placed in Service	March 2023		
Useful Life	26		
Replacement Year	48-49		
Remaining Life	24		



Shade structure and fabric projected replacement in FY 2048 as a one time replacement.

Sport Court Replacemen Asset ID	nt - 2052	2,520 Square Yards Asset Actual Cost Percent Replacement	@ \$76.50 \$192,780.00 100%
Category	Sport Courts	Future Cost	\$505,116.75
Placed in Service	June 2023		
Useful Life	30		
Replacement Year	52-53		
Remaining Life	28		

Sport Court Replacement continued...



Sport Court Resurfacing (color coat) - 2030

Asset ID		2,520 Square Yards Asset Actual Cost	@ \$9.60 \$24,192.00
		Percent Replacement	100%
Category	Sport Courts	Future Cost	\$29,738.14
Placed in Service	June 2023		
Useful Life	8		
Replacement Year	30-31		
Remaining Life	6		



Concrete Pavers - Pool Deck/Patio - 2047

Asset ID

Category Placed in Service Useful Life Replacement Year Remaining Life

Swimming Pool	
June 2008	
40	
47-48	
23	

14,570 Square Feet	@ \$7.60
Asset Actual Cost	\$110,732.00
Percent Replacement	100%
Future Cost	\$244,287.47



Fiberglass Refurbish Allow - Pool Slide - 2034

Asset ID	1020	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$29,000.00 \$29,000.00 100%
Category	Swimming Pool	Future Cost	\$40,907.36
Placed in Service	June 2023		
Useful Life	12		
Replacement Year	34-35		
Remaining Life	10		



Community Advisors Page 5-42 March 23, 2024

Filtration Equip Allowa	ance (partial replacem	ent) - 2024	
		1 Lump Sum	@ \$3,000.00
Asset ID	1025	Asset Actual Cost	\$3,000.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$3,000.00
Placed in Service	June 2008		
Useful Life	1		
Replacement Year	24-25		
Remaining Life	0		



Filtration System Refurishment Allowance - 2042

Asset ID	1025	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$30,000.00 \$30,000.00 100%
Category	Swimming Pool	Future Cost	\$55,724.67
Placed in Service	June 2008		
Useful Life	35		
Replacement Year	42-43		
Remaining Life	18		



Community Advisors Page 5-43 March 23, 2024

1

Pool Lift - 2032		1 Each	@ \$5,642.00
Asset ID	1021	Asset Actual Cost	\$5,642.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$7,429.44
Placed in Service	June 2021		
Useful Life	12		
Replacement Year	32-33		
Remaining Life	8		
	A 8 1		



ool Resurfacing/Tile -	2026	3,460 Square Feet	@ \$34.00
Asset ID	1018	Asset Actual Cost	\$117,640.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$126,018.91
Placed in Service	June 2015		
Useful Life	12		
Replacement Year	26-27		
Remaining Life	2		



Community Advisors Page 5-44 March 23, 2024

Pool Splash Equipment Allow	ance - 2027
-----------------------------	-------------

Asset ID	1017
----------	------

Category Placed in Service Useful Life Replacement Year Remaining Life

Swimming Pool
June 2008
20
27-28
3

 1 Lump Sum
 @ \$20,000.00

 Asset Actual Cost
 \$20,000.00

 Percent Replacement
 100%

 Future Cost
 \$22,174.36



Refurbish Allowance - Pool Slide Frame - 2034

Asset ID	1024	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$39,000.00 \$39,000.00 100%
Category	Swimming Pool	Future Cost	\$55,013.35
Placed in Service	June 2023		
Useful Life	12		
Replacement Year	34-35		
Remaining Life	10		



Community Advisors Page 5-45 March 23, 2024

Shade Fabric - Pool - 2	2047	3 Each	@ \$2,300.00
Asset ID	1022	Asset Actual Cost	\$6,900.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$15,222.19
Placed in Service	April 2024		
Useful Life	14		
Adjustment	10		
Replacement Year	47-48		
Remaining Life	23		

Shade fabric scheduled for replacement in FY 2024 with projected life of 14 years which occurs at time of frame and fabric replacement (seperate component). After full replacement the next replacement cycle of fabric is projected to be FY 2047.

Shade Structure Replac	cement - 2033	3 Each	@ \$15,000.00
Asset ID	1023	Asset Actual Cost	\$45,000.00
		Percent Replacement	100%
Category	Swimming Pool	Future Cost	\$61,330.38
Placed in Service	June 2008		
Useful Life	26		
Replacement Year	33-34		
Remaining Life	9		

Shade Structure Replacement continued...



Structure and fabric replacement projected in FY 2033 as a one time replacement.

Splash Pad Equipment Allowance - 2047

Asset ID

Category Placed in Service Useful Life Replacement Year Remaining Life Swimming Pool June 2023 25 47-48 23

 1 Lump Sum
 @ \$42,000.00

 Asset Actual Cost
 \$42,000.00

 Percent Replacement
 100%

 Future Cost
 \$92,656.81



Backflow Preventer Repair

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Electrical Panels/Disconnects

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Community Advisors Page 5-48 March 23, 2024



Grills continued...



Interior Painting - Clu	bhouse		
Asset ID	1074	Asset Actual Cost	
		Percent Replacement	100%
Category	Operating Expense	Future Cost	
Placed in Service	June 2008		
No Useful Life			

Laminated Beam Repair

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Community Advisors Page 5-50 March 23, 2024

Message Board

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008

7

Asset Actual Cost Percent Replacement Future Cost

100%



Painting - Entry Featu	ires		
Asset ID	1081	Asset Actual Cost	
		Percent Replacement	100%
Category	Operating Expense	Future Cost	
Placed in Service	June 2008		
No Useful Life			
Painting - Pool Equip	ment Yard		
Asset ID	1078	Asset Actual Cost	\$0.85
Asset ID	1078	Asset Actual Cost Percent Replacement	\$0.85 100%
Asset ID Category	1078 Operating Expense		
		Percent Replacement	100%

Painting - Pool Equipment Yard continued...



Pendent Lights - Breezeway

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Refrigerator

Asset ID

1034

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense June 2008

> Community Advisors Page 5-52 March 23, 2024

Refrigerator continued...



Splash Pad Coating/Repair

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Sport Court Nets/Equipment

Asset ID

Category Placed in Service No Useful Life Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%

Sport Court Nets/Equipment continued...



Trash Cans/ Misc. Site Furnishings

Asset ID

Category Placed in Service No Useful Life

No Useful Life

Operating Expense June 2008 Asset Actual Cost Percent Replacement Future Cost

100%



Water Coolers - Club	house	
Asset ID	1053	Asset Actual Cost Percent Replacement
Category Placed in Service	Operating Expense June 2008	Future Cost

100%

Community Advisors Page 5-54 March 23, 2024

Water Heater - Clubh	ouse		
Asset ID	1057	Asset Actual Cost Percent Replacement	100%
Category Placed in Service No Useful Life	Operating Expense June 2008	Future Cost	10070

Community Advisors Page 5-55 March 23, 2024

Backflow Preventer Replacement

Asset ID

Category ponents Not Included Placed in Service June 2008 No Useful Life Asset Actual Cost Percent Replacement Future Cost

100%



Building Foundation/Frame)		
Asset ID	1071	Asset Actual Cost Percent Replacement	100%
Category ponents 1	Not Included	Future Cost	
Placed in Service No Useful Life	June 2008		
Communication Wiring/Devi	ces in Building		
Asset ID	1071	Asset Actual Cost Percent Replacement	100%
Categorymponents I Placed in Service No Useful Life	Not Included June 2008	Future Cost	

			n Building	ectrical Wiring/Devices
100%	Actual Cost Replacement Future Cost	Percent Re	1071 s Not Included	Asset ID Categæymponen
			June 2008	Placed in Service No Useful Life
			rking Lot	ght Poles (Concrete) - Pa
100%	Actual Cost Replacement		1071	Asset ID
10070	Future Cost		s Not Included	Categorymponen
			June 2008	Placed in Service
				No Useful Life
				ling/Trim Replacement
	Actual Cost	Asset A	1071	Asset ID
100%	Replacement			~ ~ ~
	Future Cost	F	s Not Included June 2008	Categorymponen Placed in Service
			June 2008	No Useful Life
				_

Community Advisors Page 5-57 March 23, 2024

Site Utilities		
Asset ID 1071	Asset Actual Cost	100%
Category ponents Not Included	Percent Replacement Future Cost	100%
Placed in Service June 2008 No Useful Life		
Water/Sewer/Vent Piping In building		
Water/Sewer/Vent Piping In building Asset ID 1071	Asset Actual Cost Percent Replacement	100%

Wood Pergolas - Entry Signs	S		
Asset ID	1004	Asset Actual Cost	
		Percent Replacement	100%
Category Compone	ents Removed	Future Cost	
Placed in Service	June 2008		
No Useful Life			

Report Navigation

- **Executive Summary** provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- **Cash Flow** is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- Annual Expenditure Detail provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- **Component Detail Index** allows quick access to the detail we have included for each component separated into categories
- **Component Detail** provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk; using this method requires regular analysis updates.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. *Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.*

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

Community Advisors Page 6-2 March 23, 2024

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.

Community Advisors Page 6-4 March 23, 2024